


GROUND HANDLING BULLETIN



FEB2026

CONTENTS

AIRCRAFT HANDLING	2
SAFETY	2
<i>Anti-Collision Light Awareness – Do Not Rely on ACL Alone</i>	<i>2</i>
<i>The Importance of Reporting.....</i>	<i>3</i>
<i>Pushback Communication – Critical Safety Barriers.....</i>	<i>4</i>
PROCEDURE.....	5
<i>Post-Loadsheet Adjustments of Deadlock.....</i>	<i>5</i>
PASSENGER HANDLING	7
PROCEDURE.....	7
<i>Families with INF Added to Boarding Group 0.....</i>	<i>7</i>
<i>Change Flight on the Same Day – Altea CM (AJO)</i>	<i>11</i>

<i>Revised Prices for Excess Baggage Intercont.....</i>	<i>11</i>
<i>Automated iCoupon for Canceled Flights from the 3rd of February 2026.....</i>	<i>13</i>
<i>iAPI Interactive Advanced Passenger Information to the UK - Reminder.....</i>	<i>14</i>
<i>Baby Stroller Not Accepted as Cabin Baggage on Embraer E 195 - Reminder.....</i>	<i>18</i>
WORLDTRACER NEWS.....	19
<i>New System Prompt in Action File Matches and Matches in Files.....</i>	<i>19</i>
GENERAL	20
PROCEDURE.....	20
<i>Auto Reflight Start at ARN</i>	<i>20</i>
ABOUT GROUND HANDLING BULLETIN	21

AIRCRAFT HANDLING

SAFETY

Anti-Collision Light Awareness – Do Not Rely on ACL Alone

Over the last months, we have received several reports of the anti-collision light (ACL) being switched off before the engines are fully shut down.

The ACL is one of the most critical safety indicators for ground personnel when assessing aircraft movement status. However, it must never be used as the only indication that it is safe to enter the engine hazard area.

Always confirm safety using multiple barriers, such as:

- Listening for engine noise
- Observing the engine spinner/fan blades and confirming rotation has stopped
- Having the habit of waiting when uncertain and keeping clear until confirmed safe

Investigation findings

We have investigated these occurrences and are taking actions to prevent them. In some cases, human factors have contributed. However, we have also identified a technical condition affecting our E195 fleet.

During parking, a known fault condition may occur during the power shift from aircraft power to the GPU. In some cases, the generators may temporarily drop offline, causing a short loss of external lighting—including the ACL—even though one or both engines may still be running. During this time, one or both engines may be operating at higher power than normally permitted when the ACL is switched off.

Actions moving forward

First, thank you to all ground handlers who have submitted reports. Your reporting helps us identify safety risks early and act on them. We are working closely with Engineering and the aircraft manufacturer to resolve this technical issue.

Until further notice, all personnel must apply extra caution around engines and never enter the engine hazard area based on ACL status alone.

If there is any doubt—STOP, keep clear, and verify engine shutdown before approaching.

[Back to first page](#)

The Importance of Reporting

Introduction

Recently, an SAS aircraft was towed to the wrong parking stand. This created a maintenance requirement: the aircraft needed an inspection before it could be released to service and confirmed airworthy.

The required reporting procedure was not followed, and the flight crew were not informed. The aircraft was prepared for departure and almost left without the crew being aware of the issue. This was a serious near miss and could have led to severe consequences.

This safety notice is a reminder to all ground personnel of the importance of reporting incidents and communicating promptly, to prevent similar events in the future.

What went wrong?

- The occurrence was not reported immediately to the airline and the Flight Deck.
- Due to the lack of communication, the aircraft continued toward departure with passengers onboard, even though a maintenance inspection was required before further flight.

Actions required:

For any Ground Operations incident or accident that results in aircraft damage or injury to personnel:

- 1 STOP WORK – Do not put yourself or others at further risk.
- 2 REPORT IMMEDIATELY to:
 - a. Airline Representative
 - b. Flight Deck
- 3 Secure the scene – Prevent movement of GSE and personnel if possible.
- 4 Assist injured persons – Request medical help if needed.

- 5 Complete the Ground Incident Damage Report (AHM 650) and submit it to line management, the airline, and authorities as required.

Prompt reporting helps ensure safe operations and prevents dispatch of an aircraft that may not be airworthy.

Thank you for helping make SAS a safer airline.

[Back to first page](#)

Pushback Communication – Critical Safety Barriers

Following a recent incident where an aircraft began taxiing before all equipment and personnel were clear, we want to highlight this process and ask everyone to place extra focus on pushback and departure coordination.

The departure process—including pushback, headset communication, and engine start—is one of the most complex and highest-risk phases of the operation. It relies completely on clear and accurate communication between all parties involved. Standard phraseology and terminology must be used consistently so that everyone has the same understanding of the plan throughout the entire process.

Because the cockpit's line of sight is limited, the flight crew cannot directly observe the area behind the aircraft. This means they rely entirely on information provided by ground personnel.

What may sometimes seem like “small details” are essential safety barriers. Examples include:

- Holding up the steering by-pass pin when giving the All Clear (to taxi) signal
- Parking the vehicle in sight of the flight deck when removing the steering by-pass pin
- Verbally confirming the position where the All Clear signal will be given

Follow the IGOM departure procedure. These steps help prevent accidents. When everyone knows what they will see and hear, the departure process becomes smoother and safer. Procedures exist for a reason—and many are written in response to past incidents. Everyone involved must treat these actions with the seriousness they deserve.

Thank you for helping make SAS a safer airline!

[Back to first page](#)

PROCEDURE

Post-Loadsheet Adjustments of Deadlock

Background:

SAS is introducing a new Altea FM Mobile feature that allows the responsible personnel to adjust loading figures even after the final loadsheet has been sent—without requiring prior approval from pilots or load control.

These changes will be effective in February 2026.

The intention with this new feature is to enable additional flexibility, and to provide a simplified and more efficient way to make late adjustments. However, it comes with responsibilities and restrictions (see procedure). All existing Altea FM safety barriers remain in place, meaning that any violation will trigger a system lock, load control will have to approve the new distribution, which could cost valuable time close to departure and possibly cause an unnecessary delay.

Note: Stations not using Altea FM Mobile must continue contacting load control for changes after the final loadsheet, as per current procedures.

Procedure:


Before making post-loadsheets adjustments, ensure balance conditions, ground stability, and weight limitations are reviewed to avoid rule violations.

This procedure applies only to cargo/mail and baggage adjustments.

The following are prohibited:

- Introducing new commodities (that is not planned on LIR)
- Adding deadload to an empty compartment or net section
- Adding special loads or dangerous goods

Instruction on how to perform adjustments after final loadsheet has been sent:

Step	Action
1	<p>Verify that flight is in LSF (LoadSheet Finalized) status. If flight status is not in LSF, open the compartment and make the necessary adjustments as normal, without these steps.</p> <p></p> <p><u>Note:</u></p> <p><i>Stations that do not use Altea FM Mobile must contact Load Control in order to re-open the flight after the final loadsheet has been issued.</i></p>
2	<ol style="list-style-type: none">1. Open the desired compartment.2. Make the necessary adjustments (like normal procedures).3. Close the compartment and confirm that status is LSF again.
3	Verify that the new loadsheet has been received by the flight crew prior to off-block.

How to display the latest edition number of the loadsheet:

To display detailed flight information, tap  or select Flight Info from the Menu.





Image: Flight Information Screen



Documents

The current version number of the:

- Load Instruction Report (LIR)
- Operational Flightplan (OFP)
- Final NOTOC
- Final Loadsheet

LIR 1 - OFP 0
NOF 2 - FLT 0

[Back to first page](#)

PASSENGER HANDLING

PROCEDURE

Families with INF Added to Boarding Group 0

Background/ Introduction:

Today we have the procedure that families with Infants (INF) shall be Preboarded manually, whenever possible, according to SPM 19.3.

To make the boarding process even smoother we will add families with Infants to boarding in boarding group 0. Hopefully Earlier, calmer entry for families with infants reduces aisle congestion and speeds up boarding for other groups

The following applies:

- **From 03FEB2026** families with INF shall be boarded in boarding group 0.
- The Boarding Group 0 will be printed on the boarding card
- Altéa CM is updated accordingly, so families with INF will be sorted under boarding group 0 in Altea.
- We continue with the same neutral boarding announcement for boarding group 0.
- Passengers traveling in Go Light with carryon baggage shall be charged according to procedure, even though they board with group 0.

Boarding groups and order of boarding

The example below shows boarding groups for short haul flights to Europe.
Families with Infants added to boarding group 0

Boarding Group	Passengers
0	EuroBonus Pandion EBP and Families with Infants
1	EBD, EBG and SkyTeam Elite Plus
2	Business
3	EuroBonus Silver, SkyTeam Elite, passengers seated on Exit rows and Economy flex
4	Economy and Economy Light passengers with prepaid carry-on bag
5	Economy Light passengers





Boarding announcement for boarding group 0

The boarding announcement for boarding group 0 is the same as before


- We would like to invite passengers in boarding group 0 to come to the desk for boarding. Your boarding card is marked with group 0.

Example boarding cards:


Example PREMIUM Domestic



Example ECONOMY STANDARD



Example ECONOMY LIGHT (NO-CARRY ON)



Boarding Pass

No Carry-On Bag

BLOCK/EDYTH MS

PNR YP8R4R

Notes ARN987

Flight SK010

Date Time 21JAN 13:40

From To Stockholm Lulea

Class Gate Seq# Group Seat Boarding

Scandinavian Airlines ARN M T 1 0 21B 13:10

ECONOMY LIGHT ETKT

Ticket no 117-2536569512

Boarding Pass

No Carry-On Bag

BLOCK/SARAH

PNR YP8R4R

Notes ARN987

Flight SK010

Date Time 21JAN 13:40

From To Stockholm Lulea

Class Gate Seq# Group Seat Boarding

Scandinavian Airlines ARN M T 2 0 21A 13:10

ECONOMY LIGHT ETKT

Ticket no 117-2536569513

Boarding Pass

No Carry-On Bag

BLOCK/DINA

PNR YP8R4R

Notes ARN987

Flight SK010

Date Time 21JAN 13:40

From To Stockholm Lulea

Class Gate Seq# Group Seat Boarding

Scandinavian Airlines ARN M T 3 0 INF 13:10

ECONOMY LIGHT ETKT

Ticket no 117-2536569514

Example ECONOMY LIGHT (PREPAID CARRY-ON)

BOARDING PASS

SAS

HILL/JOHN

PNR YP8M14

Notes

Flight SK010

Date Time 21JAN 13:40

From To Stockholm Lulea

Class Gate Seq# Group Seat Boarding

Scandinavian Airlines ARN M 0 19A 13:10

ECONOMY LIGHT

Ticket number 1172536569515

PREPAID CARRY-ON BAG

BOARDING PASS

SAS

HILL/NONA

PNR YP8M14

Notes

Flight SK010

Date Time 21JAN 13:40

From To Stockholm Lulea

Class Gate Seq# Group Seat Boarding

Scandinavian Airlines ARN M 0 INF 13:10

ECONOMY LIGHT

Ticket number 1172536569517

BOARDING PASS

SAS

HILL/MAYBELLE

PNR YP8M14

Notes

Flight SK010

Date Time 21JAN 13:40

From To Stockholm Lulea

Class Gate Seq# Group Seat Boarding

Scandinavian Airlines ARN M 0 19B 13:10

ECONOMY LIGHT

Ticket number 1172536569516

PREPAID CARRY-ON BAG

09:20

JOHN HILL

Flight SK010

Terminal 5

Boarding group 0

Gate E9

Boarding time 13:10

Seat 19A

ECONOMY

Stockholm Lulea

ARN LLA

21 Jan, 13:40 1h 20m 15:00

Add to Siri

09:21

NONA HILL (Infant)

Flight SK010

Terminal 5

Boarding group 0

Gate E9

Boarding time 13:10

Seat 19A

ECONOMY

Stockholm Lulea

ARN LLA

21 Jan, 13:40 1h 20m 15:00

Add to Apple Watch

Add to Siri

09:21

MAYBELLE HILL

Flight SK010

Terminal 5

Boarding group 0

Gate E9

Boarding time 13:10

Seat 19B

ECONOMY

Stockholm Lulea

ARN LLA

21 Jan, 13:40 1h 20m 15:00

Add to Apple Watch

Add to Siri

Boarding Pass

Prepaid Carry-On Bag

HILL/JOHN MR

PNR YP8M14

Notes ARN987

Flight SK010

Date Time 21JAN 13:40

From To Stockholm Lulea

Class Gate Seq# Group Seat Boarding

Scandinavian Airlines ARN M T 5 0 19A 13:10

ECONOMY LIGHT ETKT

Ticket no 117-2536569515

Boarding Pass

Prepaid Carry-On Bag

HILL/NONA

PNR YP8M14

Notes ARN987

Flight SK010

Date Time 21JAN 13:40

From To Stockholm Lulea

Class Gate Seq# Group Seat Boarding

Scandinavian Airlines ARN M T 6 0 INF 13:10

ECONOMY LIGHT ETKT

Ticket no 117-2536569517

Boarding Pass

Prepaid Carry-On Bag

HILL/MAYBELLE MS

PNR YP8M14

Notes ARN987

Flight SK010

Date Time 21JAN 13:40

From To Stockholm Lulea

Class Gate Seq# Group Seat Boarding

Scandinavian Airlines ARN M T 4 0 19B 13:10

ECONOMY LIGHT ETKT

Ticket no 117-2536569516

[Back to first page](#)

Change Flight on the Same Day – Altea CM (AJO)

Effective 28JAN2026 Altea CM Business rules are updated for **Available Journey Option**.

Use Available Journey Option in Altea CM for customers holding Flex tickets eligible to change flight on the same day.

The system now checks if the customers' Fare Basis in the ticket is eligible for the flight change free of charge. If so, flights available earlier and/or later will be shown and can be selected.

Note:

If no flights are shown, there are no more available seats on this day.

[Back to first page](#)

Revised Prices for Excess Baggage Intercont

Effective **28JAN2026** the prices for excess baggage will be changed.

Excess Rates – Additional Pieces – Less than 22 hours before departure

The table below shows the excess rates for extra/additional pieces of baggage, within the standard weight limit: New prices under Intercont marked in **Yellow**.

Service class	Weight	Domestic	Europe including Greenland & Intranscand	Intercont (USA, ASIA, Lebanon)
Premium Economy	Max 23 kg	EUR 55 SEK 540 NOK 540 DKK 450 USD 65	EUR 75 SEK 690 NOK 690 DKK 570 USD 85	EUR 120 SEK 1299 NOK 1299 DKK 895 USD 140 CAD 195
Business	Max 32 kg	N/A		

Excess Rates – Exceeding the Weight Limit

Standard, Premium or Business (ABAG is always the first bag outside allowance)

	EUR	SEK	NOK	DKK	USD	CAD
First checked bag (ABAG)	90	969	969	679	106	145

	EUR	SEK	NOK	DKK	USD	CAD
2nd checked bag (BBAG)	95	1029	1029	709	112	155

	EUR	SEK	NOK	DKK	USD	CAD
3rd or more checked bags (CBAG)	95	1029	1029	709	112	155

	EUR	SEK	NOK	DKK	USD	CAD
STATION & ABAG/BBAG/CBAG	120	1299	1299	895	140	195

Changes within 22h from dep also apply to Lebanon (BEY)

[Back to first page](#)

Automated iCoupon for Canceled Flights from the 3rd of February 2026

Previously we have activated automated iCoupon for delayed flights. We will now continue with automated iCoupon for canceled flights. This is for all stations where we have iCoupon implemented, at the moment more than 100 stations.

The iCoupon will be automatically triggered when ASM CNL is sent if the flight is canceled less than six hours before STD.

Customers on flights that are canceled will receive SMS and email with an iCoupon as QR code. It is only the QR code in the separate SMS/email that is valid for usage, i.e. no boarding pass can be used. Each passenger will receive a message if there is more than one customer in the booking.

The SMS and email will contain a link to fetch the QR code and a link which locations can be used for the specific airport where the flight cancellation has occurred.

The value of the iCoupon will be according to the set table.

If customers haven't received the iCoupon, line stations can contact GlobalLineStationSupport to be assisted. Hubs can manually activate canceled Stand Alone iCoupon if not received.

Activation will be on the 3rd of February 2026.

[Back to first page](#)

iAPI Interactive Advanced Passenger Information to the UK - Reminder

Introduction

In NOV2024, DEC2024 and APR2025 we have informed you regarding the new border and immigration system developed by The UK Home Office. The system has been implemented gradually and previously boarding has not been refused to passengers who did not have a valid ETA. This will now be changed.

The following applies

From dates below the implementation period is ended and eVisa and ETA enforced.

- Effective **28JAN2026** iAPP will query all visa required nationals for an eVisa
- Effective **25FEB2026** iAPP will query all non-visa nationals for an ETA


Links:

- ETA [show more about ETA](#)
- eVisa [show more about eVisa](#)

If an eVisa or ETA is registered with the passport, customer is **OK TO BOARD**.

Passport or travel documents and identity check are still to be performed.

'0A – Valid Permission to Travel'

Response message	Action
 VALID PERMISSION TO TRAVEL	<p>This confirms that the individual has a valid digital immigration permission (either an ETA or an eVisa), and no further immigration checks are required.</p> <p>Carriers must continue to check that the passport or travel document held by the passenger is valid, genuine, and in the possession of the rightful holder in all cases.</p>

Introduction of 0B – No Record of Valid Permission

Introduction of “0B - No Record of Valid Permission”

The '0B - No Record of Valid Permission to Travel' response will be introduced into iAPI systems in **two phases**, as part of a global switch-on for all UK inbound flights.

January 2026	February 2026	March 2026	April 2026
	28th January 2026: 0B for Visa Nationals: Conduct manual check for permission to travel		
ETA Implementation Period		25th February 2026: 0B for Non-visa Nationals: Passenger must apply for an ETA	


- Some **visa national passengers** may still only have a physical document proving their visa or permission to travel. In these cases, presenting a valid, genuine, physical proof of permission will remain satisfactory evidence of a passenger's permission to travel to the UK.
- Non-visa national passengers** may have an alternative permission they can evidence.

If iAPP returns No Valid Permission in Altea CM, the following checks to be performed:

Resolving a 'No record of valid permission to travel'



Altea CM iAPP responses:



iAPP Check Status		
SK407	23JAN	ARN-CPH
iAPP STATUS - Checks not required		
GBR-Security Status: OK to Board		
CARRIER MAY CONDUCT MANUAL CHECK TO DETERMINE PERMISSION		
SK1501	23JAN	CPH-LHR
GBR-Immigration Status: No Valid Permission		

If an update to the UKVI account cannot be completed and customers hold physical documents proving their permission to enter the UK, add visa details in Altea CM:

Visa

Qualifier:	Visa
Feature:	
Country:	GBR
Number:	BB33423232
Surname:	SMITH
Given Name(s):	Siw
Date of Issue:	11NOV2019
Issue Country:	GBR
Expiry Date:	12DEC2032
Carried:	Yes
Valid From:	
Valid To:	
Nbr days permitted:	
Nbr days permitted/entry:	

Basic Options [F2] **Confirm**

And perform iAPP override:

PDI | **Flight Information** | **Customer List Selection** | **Customer List** | **Customer Selection** | **Customer Acceptance**

Search: SK407 23JAN ARN (5) CPH Copenhagen Kastrup (3) Gate: None Boarding: 17:30

Customer	Bkg Tkt Cabin	Sec	Seat	Accept Baggage	Info
1 SMITH Siv Ms	SK407	23JAN	ARN-CPH	C(C)	SK-8IZ, CTOM, CTCE
	SK1501	23JAN	CPH-LHR	C(C)	SK-8IZ, iAPP, CTOM, CTCE

Select Customer(s) for Acceptance: 1 Expand [SF2] 1 of 1 Selected

iAPP Clearance is required for customer: SMITH Siv Ms. Manual action required or change the flight/leg selection.

Additional Travel Requirements

- Check Requirements AF11
- Blacklist
- Blacklist Override SF11
- Documentation
- Add or Amend Multiple Passports CF4
- Add or Amend Travel Document CF8
- Add Secondary Document F5
- Delete Travel Information CF9
- Regulation Authority
- Check ADC F7
- Check APP F11
- Check AQQ SF3
- Check iAPP F10
- Override ADC SF8
- Override AQQ/ESTA-DocVal SF2
- Override iAPP CF12

Advanced Options [F2] Exit

Enter iAPP override data for the selected customer(s).

iAPP Override

Country: United Kingdom

Status type: Immigration

Authoriser: [Redacted]

OT – System Timeout

From 28th January 2026, we will also be introducing the 'OT – System Time Out' response.

This will be sent when Home Office systems are taking longer than expected to respond to a permission check request from a carrier.

If you receive a 'OT – System Timeout' Response:

1. Make an **initial resubmission attempt**.
2. If this and any subsequent resubmission attempts are unsuccessful, carriers should make a **final resubmission attempt** no later than one hour prior to scheduled time of departure.
3. If you still receive a 'OT' response, the **passenger may be boarded** and there will be no carrier liability for their permission to travel.

However, you must still ensure that the passenger's travel document is valid, genuine and held by the rightful owner.

If the outage is on your carrier side, you must contact the Carrier Support Desk to advise them of the outage

+44 300 106 5216 or CarrierSupport@homeoffice.gov.uk



[Back to first page](#)

Baby Stroller Not Accepted as Cabin Baggage on Embraer E 195 - Reminder

Introduction

For a long time, we have had challenges with accommodating baby strollers in the cabin of the E195. There is slightly less space in the overhead compartment and under the front seat on this aircraft type. This has led to problems and the necessity to move the stroller down to the cargo area, which in turn has led to discussions and delays.

Effective immediately

With immediate effect we only allow baby strollers of the umbrella type with maximum measures 20x20x100 cm as cabin baggage on E 195.

All other types of collapsible stroller are no longer permitted in the cabin on Embraer E195.

Permitted as cabin baggage on E 195

Small stroller.



Figure 23.3.3-1:

Dimensions in this example: 20 × 20 × 100 cm.

Details:

- Maximum weight 8 kg.
- Must be fully collapsible as in the picture above.
- Strollers with additional parts, such as hood, basket, umbrella, are not allowed into the cabin.



[Back to first page](#)

WORLDTRACER NEWS

New System Prompt in Action File Matches and Matches in Files

SITA has introduced a new System Prompt for the Station Inbox (Action File) under System Matches.

As E-mail Address (EA) is a unique matching element as no e-mail addresses are even.

To assist the agents to look at a match even if the matching score is under minimum score of 55 %, the system will trigger a prompt to look at a match with similar e-mail.

This also means, that it is not allowed to enter random e-mail addresses like [no@mail.com](#), [no@no.com](#) and similar -either in Delayed Bag files nor in On-Hand files. Please do not ever “make up” an e-mail just to fill the field.

E-mail addresses are not mandatory with SK, but we do expect that all passengers are asked for this to be updated in the file. Both for tracing and matching but also for informing passengers with automated e-mails.

[Back to first page](#)

GENERAL

PROCEDURE

Auto Reflight Start at ARN

SAS has started Auto Reflight at ARN. All stations may be affected

What does this mean:

- Rush will be done faster.
- CM and FM are updated as a manual Rush
- SAS will use the same tag number. It is a big advantage for our passengers that they will be able to see in the SAS App which flight their bag is Auto Reflighted on. It also reduces the use of paper, which is positive.
- This means for loading that tags always have to be scanned to see the updated information, as no visible rush tag will be printed.
- From the start, SAS will only Auto Reflight baggage, that was supposed to go on a SK flight - both from SK and from OAL if it is seen in the baggage sorting system in CPH.

For more information – See attachment.

Please inform those concerned at your stations.

If you have any questions, please contact peter-e.stenqvist@sas.se.

For more information - see presentation from SITA attached (the article is located last in the bulletin):

SITA Auto Reflight with Roadmap

[Back to first page](#)

ABOUT GROUND HANDLING BULLETIN

The contents of this Bulletin are published by SAS Operations Services Ground Handling.

Use your normal point of contact if there is anything you have questions about, or want to include, in the Ground Handling Bulletin.

You can also find Ground Handling Bulletins that are applicable to you on [SASINTRA](#) and on [SAS Partner Portal](#)

Editor: Susanne Birge, STOQA-D, Mail: sasgroundhandling@sas.se

[Back to first page](#)



SITA Auto Reflight

Transfer mishandling is the top reason for delayed bags

46%

Transfer mishandling

16%

Failure to load

14%

Ticketing error/bag switch /security/other

8%

Airport/customs/weather/ space-weight restrictions


8%

Loading error

4%

Arrival mishandling


Building a process aligned to the passenger journey



IATA industry initiatives for 2024 onwards



Baggage Automation



White Paper

Baggage Auto-Reflighting: Resolution 755 - Call to Action

Actions and Recommendations

Airlines should collaborate closely with suppliers and vendors, including those responsible for Departure Control Systems (DCS), Baggage Reconciliation Systems (BRS), and tracing systems, to adopt IATA Resolution 755. This resolution, which has been in place since 2019, through the updates made in 2023, now permits automated baggage reflighting and e-rush process. Swift adoption is crucial to address the rising baggage irregularities associated with the rising global passenger traffic. Establishing strong partnerships between airline members and vendors is essential. Members are encouraged to proactively engage with their partners and vendors to implement solutions that fully leverage auto-reflighting benefits. Similarly, vendors should proactively enhance their solutions to meet the standards set by Resolution 755, enabling seamless end-to-end baggage auto-reflighting.

h their
rdized
among
ts and
ggage

Sita Auto Reflight


SaaS solution capable of reflighting bags on the original tag, without human intervention. WorldTracer Auto Reflight provides the ability to manage the mishandled bag process from end-to-end and following system configurations based on airline requirements

Requirements


- Baggage Information Messages
- Passenger information
- Flight Schedule Information
- Integration with WorldTracer

How does it work?

1. Detects a **mishandled** bag
2. Identifies a suitable **RUSH** flights following customer configurations
3. Generates Baggage Information Messages
4. Identifies RL code and FS
5. Informs **WorldTracer**
6. Helps reunite Bag with PAX




End-to-end Mishandled baggage management



Experienced BENEFITS

ACHIEVEMENTS



High automation rate

Expedited reflight

Platform agnostic

DCS, BHS, BRS

BENEFITS




No more baggage tag
reprint

Faster training

Pax waiting times cut by
50%

FINANCIAL INCENTIVES




Positive Customer ROI

RL auto coding supports
proration

Carbon emissions and paper
waste savings

Breakdown of reasons for manual processing



Automate new scenarios

More reflight on the original tag

Enhance RUSH flight selection

Leverage alliances and partnerships

Support Arrivals

Auto Reflight - Roadmap for 2025-2026



Bag Monitor

Real-time visibility of bags and flexible process management via UI

Semi-Automated RUSH on the original tag when the bag is not physically present

Disruption Mode to process large volumes of bags quickly



Additional Reflight Scenarios

Solve additional MHB scenarios to increase the overall automation rate beyond 90%

Automate additional RL codes to enable trust and support proration

Maximize the use of available aircraft capacity for RUSH bags on selected flights / destinations



Data Analytics and Reports

Simple access to historical data and analytics


Customer-facing dashboard enabling customers to track service performance



Self-Managed Product Configuration

Effortless product configuration to facilitate change requests with no downtime

Why SITA WorldTracer Auto Reflight




Focus on Automation

- High Automation Rate
- Reason for Loss auto-coding



Portability

- Cloud based Solution
- Delivered in SaaS
- Platform agnostic
DCS, BHS, BRS
- RESO 755 compliant




Flexibility and Configurability

- Bag Identification and Validation
- Bag status
- RUSH flight selection
- Load limits
- Connection type
- MCT
- Exclusion lists: Dest., flights, Bag type



Innovative Roadmap

- Semi-Automated RUSH
- Disruption mode
- Data Analytics
- Self-managed configuration



End-to-end management

- Pax Auto Notify, Self-Service, BDS
- AirTag integration
- Digital Customs declaration
- Auto BDO

In summary



Process digitalization to mitigate Customer's major pain points

- Happy passengers, informed and in control, even when something goes wrong
- Automation, to repatriate bags proactively and faster despite staffing shortage
- Reduced costs of mishandling baggage
- Sustainable operations and optimized routes



Open, scalable solution leveraging industry standards

- Fully automated cloud solution
- Allowing for smooth and fast deployment at over 2000 airports worldwide
- IT platform agnostic, compliant with IATA R755 and RP1745
- Fully integrated with SITA WorldTracer suite for end-to-end baggage management

An aerial photograph of a lush green golf course. A large, dark, irregularly shaped pond is the central feature, surrounded by green grass and some trees. In the upper left, a small, dark building is visible on a small island. The foreground shows the green grass of the golf course, with a shadow of an airplane cast on it. The text "Thank you" is overlaid in the center.

Thank you

Want to know more?



SITA

SITA Baggage Portfolio

