

TO : ALL STATIONS
FROM : GROUND OPERATIONS SMS MANAGEMENT
ISSUE DATE : 12.03.2026
SUBJECT : HOLD CEILING LIMIT- SAFA FINDING

Dear Partners,

A recent observation has been reported as a SAFA safety finding, where a cargo box exceeded the cargo compartment ceiling limit line and approached the ceiling.

This situation may pose a potential risk to the aircraft smoke detection and fire suppression systems.

Please ensure the following safety requirements are strictly applied during loading operations:

- All related personnel must be reminded of the “Pegasus Cargo Compartment Ceiling Limit Procedure.”
- All cargo must be loaded in a way that maintains a minimum clearance of 6 cm between the cargo and the cargo compartment ceiling.
- Cargo floor load limits and all applicable loading limitations must be strictly observed during the loading process.
- Adequate clearance between the cargo and the aircraft cargo compartment ceiling must always be ensured to prevent obstruction or damage to the smoke detection and fire suppression systems.
- Risky loading configurations that may be affected by aircraft movements during flight must be avoided.
- Before closing the aircraft cargo compartments, the final loading condition must be checked and approved by the person responsible for loading supervision / final inspection.

Compliance with Pegasus Airlines loading procedures and safety requirements is essential to ensure safe operations.

