


<div> <b>Condor</b></div> <div>Loading Instruction A320-200</div>	Flight Number X3815P/19	Routing FRA HAJ	Flight Date (LT) 19MAY24	Edition No. 01	Prepared By Lukas, Jeziorsky Phone: 000420221101281 clc@condor.com																															
	Registration D-AICP	Version M180	STD (LT) 14:00	Date/Time of Issue (LT) 19MAY24 11:55																																
<div>On Arrival</div> <div><div><div>5</div><div>4</div><div>3</div><div>1</div></div><div></div></div>																																				
<div>At Departure</div> <div><div><div>5</div><div>4</div><div>3</div><div>1</div></div><div><div>NIL</div><div>NIL</div><div>NIL</div><div>NIL</div></div><div><div>DOOR</div><div>DOOR</div><div>DOOR</div></div></div>																																				
<div>Joining Load</div> <table><tr><td>DEST</td><td>PAX</td><td>B</td><td>C</td><td>M</td><td>OTHER</td></tr><tr><td>HAJ</td><td>0</td><td>0/0pcs</td><td>0</td><td>0</td><td>0</td></tr></table>		DEST	PAX	B	C	M	OTHER	HAJ	0	0/0pcs	0	0	0	<div>Deadload Summary</div> <table><tr><td>TTL</td><td>CPT 5</td><td>CPT 4</td><td>CPT 3</td><td>CPT 1</td></tr><tr><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td></tr></table>		TTL	CPT 5	CPT 4	CPT 3	CPT 1	0	0	0	0	0	<div>C.G. Limits</div> <table><tr><td></td><td>FWD</td><td>AFT</td></tr><tr><td>LIZFW 49.5</td><td>42.1</td><td>73.7</td></tr><tr><td>LITOW 49.4</td><td>38.0</td><td>67.2</td></tr></table> <div>Underload 19885</div>			FWD	AFT	LIZFW 49.5	42.1	73.7	LITOW 49.4	38.0	67.2
DEST	PAX	B	C	M	OTHER																															
HAJ	0	0/0pcs	0	0	0																															
TTL	CPT 5	CPT 4	CPT 3	CPT 1																																
0	0	0	0	0																																
	FWD	AFT																																		
LIZFW 49.5	42.1	73.7																																		
LITOW 49.4	38.0	67.2																																		
<div>Special Instructions</div>		<div>(*) Special Load</div>		<div>This aircraft has been loaded in accordance with company instructions including the deviations recorded. Load has been secured and compartments have been found free of items which do not belong there. Actual loading conditions were crosschecked with loadsheet data.</div> <div>Signature of person supervising the loading</div>																																