

GROUND SAFETY BULLETIN




INCORRECT LOADING

All staff are reminded of the importance of strictly adhering to the instructions specified in the MEL (Minimum Equipment List) when preparing the LIR and Loadsheets, in order to ensure the safety of operations.



A/C	WO	Description
DSX	928848201	AFTER CARGO INOPERATIVE



-31/AKH14 [REDACTED]AZ [REDACTED] 82/X
-32/AKH [REDACTED]0AZ [REDACTED] 82/X
-41/AKH12 [REDACTED]AZ [REDACTED] 82/X
-42/AKH [REDACTED]96AZ [REDACTED] 59/X
51 [REDACTED]77/D
-52.NIL
-53.NIL
SI

This bulletin is published by the Safety Department and intended for the promotion of the Safety culture. Its content is complementary to and does not supersede nor modify current Operations Manual provisions. The content of this Safety Bulletin is confidential: reproduction and/or distribution requires specific written approval by ITA Airways. Any clarification or information request can be forwarded to: sicurezza.volo@ita-airways.com