

GROUND SAFETY BULLETIN



ULD: DOORS & CURTAINS (ref. HLM 9.1.1)

ULD doors and curtains must be CLOSED and LOCKED prior to being loaded into the aircraft.



This bulletin is published by the Safety Department and intended for the promotion of the Safety culture. Its content is complementary to and does not supersede nor modify current Operations Manual provisions. The content of this Safety Bulletin is confidential: reproduction and/or distribution requires specific written approval by ITA Airways. Any clarification or information request can be forwarded to: sicurezza.volo@ita-airways.com