



# TUI Airline Ground Operations

## Safety Alert

### TUI Arrival Anti Collision Beacon (ACB) Procedure

Notice: GOSA25-002  
Page 1 of 1

To: All stations  
From: Paul Cowley, Regulations & Standards Specialist  
Approved by: Jan Timmermans, Head of Network Operations  
Nial Mclean, Head of Station Operations  
Kay Bartels, Deputy Nominated Person Ground Operations TUI  
Hans de Greef, Nominated Person Ground Operations JAF  
Al Pease, Nominated Person Ground Operations TOM  
Helena Sahlin, Nominated Person Ground Operations BLX  
Amber Hoogendoorn, Nominated Person Ground Operations TFL

**Applicability:** TUI Airways (TOM-BY) / TUIfly Nordic (BLX-6B) / TUI fly Belgium (JAF-TB) / TUI fly Netherlands (TFL-OR) / TUIfly Germany (TUI-X3)

Date of Publication: 14 APR 2025

Validity Period: 14 APR 2025 – UFN

#### **ATTENTION:**

#### **ACB is switched off before the engines have fully spooled down**

This Safety Alert is issued to raise awareness of the increased risk to ground personnel due to a change in Flight Crew procedures.

Following a recent change to the TUI Flight Crew Shutdown procedure, the Anti-Collision Beacon (ACB) is switched off much earlier than before the change - normally 3-4 seconds after fuel is cut off to the engines.

This means that the engines are still rotating at a high speed when the ACB is switched off. In accordance with GOM 4.1.3, personnel must not approach the aircraft until the engines are confirmed to be spooling down to a safe speed and the ACB is switched off.

Thank You

Kind regards,

TUI Airline Ground Operations