

**SPECIAL LOAD – NOTIFICATION TO CAPTAIN**

|                     |                |          |                        |                   |
|---------------------|----------------|----------|------------------------|-------------------|
| Station of Loading: | Flight Number: | Date:    | Aircraft Registration: | Reported By:      |
| FRA                 | PC94           | 27/07/25 | TCRFC                  | Mrs. Maryem Deler |

**DANGEROUS GOODS**

| Station of unloading | Airwaybill number | Proper shipping name               | Class or Division for class 1 Compat. grp | UN or ID number | Sub Risk | Number Of Packages | Net quantity | Radio Active | Radioactive Category | Packing Group | Dims | Code | CAO (x) | DRILL  | Loaded   |
|----------------------|-------------------|------------------------------------|---|-----------------|----------|--------------------|--------------|--------------|----------------------|---------------|------|------|---------|--------|----------|
|                      |                   |                                    |   |                 |          |                    |              |              |                      |               |      |      |         | ULD ID | Position |
| SAW                  | 62452288364       | HUMAN REMAINS OF BANDAR ALZIBAN NR | 1   | 120             |          |                    |              |              |                      |               |      | HUM  |         | BULK   |          |

**OTHER SPECIAL LOAD**

| Station of unload | Airwaybill Number | Content and Description | Number of packages | Quantity | Supplementary Information | Code | Landed                     |
|-------------------|-------------------|-------------------------|--------------------|----------|---------------------------|------|----------------------------|
|                   |                   |                         | 1                  | 120      | Natural cause of death    | HUM  | ULD ID<br>Position<br>BULK |

\*There was no evidence of any damaged to or leaking from the packages or any leakage from the unit load devices loaded on the aircraft.\*

|                                |                     |                            |
|--------------------------------|---------------------|----------------------------|
| Loading Supervisor's Signature | Captain's Signature | Other Information:         |
| Total TI<br>Total ICE          | 0,011<br>0kg        | 27/07/2025 11:50 AM 1 of 1 |