


MANIFEST
ICAO ANNEX 9 APPENDIX 3

FLIGHT NO.	: PC 1020	6SEP2025	12:35	PAGE : 1/1
AIRCRAFT REG. NO.	: TCRFA			
POINT OF LADING	: MUC	POINT OF UNLADING	: SAW	
CARRIER	: Pegasus			security checked

AWB	PCS/TTL	NATURE OF GOODS	WGT/KG	ORIG	DEST	CI	SPLs	REMARKS
BULK								
624 52341181	2/2	COURIER MATERIAL	34,8	MUC	EVN	X	RMD, SPX	
TOTAL BULK	2		34,8					

TOTAL	2		34,8					

ULD/Bulk Load Weight Statement




Airline PC	Flight No. PC 1020	Date 06-09-2025	Registration TCRFA	Destination SAW
---------------	-----------------------	--------------------	-----------------------	--------------------

T	ULD	Contour No	Height Code	Gross Weight	ULD Info Type / Side	cm	cm	cm	for ULD	SHC	ULD Dest	Remarks	LC
---	-----	---------------	----------------	--------------	-------------------------	----	----	----	---------	-----	-------------	---------	----

Total ULD Weights: 0,00

Trolly Nbr	Gross Weight	Remarks	SHC	Unloading Point	LC
22187	35,00		RMD, SPX	SAW	C

Total BULK Weights: 35,00



CARGO GATE

SPECIAL LOAD - NOTIFICATION TO CAPTAIN

Station of Loading	Flight Number	Date	Aircraft Registration	Prepared by	Remark
MUC	PC 1020	06SEP2025	TCRFA	Fretz	

DANGEROUS GOODS

Station of Unload	Air Waybill Number	Proper Shipping Name	Class or Div. (Sub Risk)	UN/ID Nr	Erg Code	Nbr. of Pkge	Net Qty or Tl per Pkge	RAD Cat.	PG	IMP Code	CAO [X]	ULD/ID-No.	POS
SAW	624 52341181	CONSUMER COMMODITY	9	ID 8000	9L	1	12 kg			RMD		BULK	
SAW	624 52341181	CONSUMER COMMODITY	9	ID 8000	9L	1	29 kg			RMD		BULK	

There is no evidence that any damaged or leaking packages containing dangerous goods have been loaded on the aircraft

OTHER SPECIAL LOAD

Station of Unload	Air Waybill Number	Contents and Description	Nbr. of Pkge	Net Qty per Pkge	Supplementary Information	IMP Code	ULD/ID-No.	POS
No other special load information available								

Captain's Signature:

LOADING CERTIFICATION

I certify that these articles have been loaded in accordance with all regulations and that there is no evidence of leaking or damaged packages. (to be signed by Loadcontroller)

Loading Supervisor's name and signature