

Topic: GPU PROTECTIVE RING or STRAIN RELIEF STRAP

Dear All,

I share with you this R&S, because on 12JUL23 Hisky Aircraft had a LBA inspection. The Inspector made a verbal observation that GPU connector was plugged without having the protective ring attached to secure the GPU cable.

On your operation please be ensure that Strain Relief Strap is plugged, when the GPU is connected. Otherwise, GPU can fall, and connection will be cut, and it can cause an electrical issue in cockpit!



Strain Relief Strap keeps the AGPU adapter from falling on the ground by its own weight. It hooks the AGPU cable with aircraft body.