

Click here to
acknowledge receipt

easyJet

STATION INSTRUCTION

Station Instruction #	SI 293		
Title	Seat Maps		
Date of Issue	29 th February 2024		
Effective start date	05 th March 2024		
Effective end date	UFN		
Written by	Callum Hutchinson		
Reviewed by	Nicholas Pelham	OPR No	n/a

The contents of this document are highly confidential and must not be shared with anyone else, except strictly for the purposes of providing ground handling services to easyJet. Copyright and all other intellectual property rights in the material belong to easyJet Airline Company Limited.

Reason for Issue

Seat maps for all easyJet aircraft types have been created to enable Ground Handling Partners to ensure that the correct seating configuration is set in local departure control systems.

GHM Amendments

Section	Title	Details
Appendix H (New appendix)	Seat Maps	Addition of seat maps for all aircraft types

This SI makes a change to the published Ground Handling Manual (GHM). The SI folder should have this instruction placed in it until its effective end date. GOM, GHP & other parties must ensure effective implementation of this SI at a local level. The accountable staff member at each airport must confirm to their easyJet Manager that the SI has been understood and embedded with all applicable Ground Crew. Local cascade may include some or all of the following:

- a signed read and brief, regular team briefing sessions to ensure Ground Crew understand SI content
- specific training and assurance of content comprehension by Ground Crew
- review of local audit checklists & training material to include any changes

STATION INSTRUCTION



A321 235Y SEAT MAP

CABIN ZONE	ROW	A	B	C	D	E	F
	1	UF/R	UF/R	UF/R			
	2	UF	UF	UF	UF/R	UF	UF
	3	UF	UF	UF	UF	UF	UF
	4	UF	UF	UF	UF	UF	UF
OA 1-10 (Max 57)	5	UF	UF	UF	UF	UF	UF
	6	UF	UF	UF	UF	UF	UF
	7	UF	UF	UF	UF	UF	UF
	8	UF	UF	UF	UF	UF	UF
	9	X	X	X	X	X	X
	10	X	X	X	X	X	X
	11	X	X	X	X	X	X
	12	X	X	X	X	X	X
	13	X	X	X	X	X	X
	14	X	X	X	X	X	X
OB 11-20 (Max 60)	15	X	X	X	X	X	X
	16	X	X	X	X	X	X
	17	X	X	X	X	X	X
	18	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	19	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	20	X	X	X	X	X	X
	21	X	X	X	X	X	X
	22	X	X	X	X	X	X
	23	X	X	X	X	X	X
	24	X	X	X	X	X	X
OC 21-31 (Max 64)	25	X	X	X	X	X	X
	26	X	X	X	X	X	X
	27	X	X	X	X	X	X
	28		R	R	X	X	
	29	R	R	R	R	R	R
	30	X	X	X	X	X	X
	31	X	X	X	X	X	X
	32	X	X	X	X	X	X
	33	X	X	X	X	X	X
	34	X	X	X	X	X	X
	35	X	X	X	X	X	X
OD 32-40 (Max 54)	36	X	X	X	X	X	X
	37	X	X	X	X	X	X
	38	X	X	X	X	X	X
	39	X	X	X	X	X	X
	40	X	X	R	R	X	X

Notes:

*R – RESTRICTED SEATING (CHIPPED) – REFER TO GHM 1.1.4.3

*X – STANDARD SEAT

*UF – UPFRONT SEATING

*EL – EXTRA LEGROOM SEATING

*ONLY 1 INFANT PER ROW OF 3 SEATS PERMITTED - E.G 1 INFANT IN ABC AND 1 INFANT IN DEF (INFANTS CANNOT OCCUPY RESTRICTED SEATS)

This SI makes a change to the published Ground Handling Manual (GHM). The SI folder should have this instruction placed in it until its effective end date. GOM, GHP & other parties must ensure effective implementation of this SI at a local level. The accountable staff member at each airport must confirm to their easyJet Manager that the SI has been understood and embedded with all applicable Ground Crew. Local cascade may include some or all of the following:

- a signed read and brief, regular team briefing sessions to ensure Ground Crew understand SI content
- specific training and assurance of content comprehension by Ground Crew
- review of local audit checklists & training material to include any changes

STATION INSTRUCTION



A320 186Y SEATMAP

CABIN ZONE	ROW	A	B	C	D	E	F
	1	UF/R	UF/R	UF/R	UF/R	UF	UF
	2	UF	UF	UF	UF	UF	UF
	3	UF	UF	UF	UF	UF	UF
	4	UF	UF	UF	UF	UF	UF
OA 1-10 (Max 60)	5	UF	UF	UF	UF	UF	UF
	6	UF	UF	UF	UF	UF	UF
	7	X	X	X	X	X	X
	8	X	X	X	X	X	X
	9	X	X	X	X	X	X
	10	X	X	X	X	X	X
	11	X	X	X	X	X	X
	12	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	13	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	14	X	X	X	X	X	X
OB 11-20 (Max 60)	15	X	X	X	X	X	X
	16	X	X	X	X	X	X
	17	X	X	X	X	X	X
	18	X	X	X	X	X	X
	19	X	X	X	X	X	X
	20	X	X	X	X	X	X
	21	X	X	X	X	X	X
	22	X	X	X	X	X	X
	23	X	X	X	X	X	X
	24	X	X	X	X	X	X
OC 21-31 (Max 66)	25	X	X	X	X	X	X
	26	X	X	X	X	X	X
	27	X	X	X	X	X	X
	28	X	X	X	X	X	X
	29	X	X	X	X	X	X
	30	X	X	X	X	X	X
	31	X	X	R	R	X	X

Notes:

*R – RESTRICTED SEATING (CHIPPED) – REFER TO GHM 1.1.4.3

*X – STANDARD SEAT

*UF – UPFRONT SEATING

*EL – EXTRA LEGROOM SEATING

*ONLY 1 INFANT PER ROW OF 3 SEATS PERMITTED - E.G 1 INFANT IN ABC AND 1 INFANT IN DEF (INFANTS CANNOT OCCUPY RESTRICTED SEATS)

This SI makes a change to the published Ground Handling Manual (GHM). The SI folder should have this instruction placed in it until its effective end date. GOM, GHP & other parties must ensure effective implementation of this SI at a local level. The accountable staff member at each airport must confirm to their easyJet Manager that the SI has been understood and embedded with all applicable Ground Crew. Local cascade may include some or all of the following:

- a signed read and brief, regular team briefing sessions to ensure Ground Crew understand SI content
- specific training and assurance of content comprehension by Ground Crew
- review of local audit checklists & training material to include any changes

STATION INSTRUCTION



A320 180Y SEATMAP

CABIN ZONE	ROW	A	B	C	D	E	F
	1	UF/R	UF/R	UF/R	UF/R	UF	UF
	2	UF	UF	UF	UF	UF	UF
	3	UF	UF	UF	UF	UF	UF
	4	UF	UF	UF	UF	UF	UF
OA 1-10 (Max 60)	5	UF	UF	UF	UF	UF	UF
	6	UF	UF	UF	UF	UF	UF
	7	X	X	X	X	X	X
	8	X	X	X	X	X	X
	9	X	X	X	X	X	X
	10	X	X	X	X	X	X
	11	X	X	X	X	X	X
	12	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	13	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	14	X	X	X	X	X	X
OB 11-20 (Max 60)	15	X	X	X	X	X	X
	16	X	X	X	X	X	X
	17	X	X	X	X	X	X
	18	X	X	X	X	X	X
	19	X	X	X	X	X	X
	20	X	X	X	X	X	X
	21	X	X	X	X	X	X
	22	X	X	X	X	X	X
	23	X	X	X	X	X	X
	24	X	X	X	X	X	X
OC 21-30 (Max 60)	25	X	X	X	X	X	X
	26	X	X	X	X	X	X
	27	X	X	X	X	X	X
	28	X	X	X	X	X	X
	29	X	X	X	X	X	X
	30	X	X	R	R	X	X

Notes:

*R – RESTRICTED SEATING (CHIPPED) – REFER TO GHM 1.1.4.3

*X – STANDARD SEAT

*UF – UPFRONT SEATING

*EL – EXTRA LEGROOM SEATING

*ONLY 1 INFANT PER ROW OF 3 SEATS PERMITTED - E.G 1 INFANT IN ABC AND 1 INFANT IN DEF (INFANTS CANNOT OCCUPY RESTRICTED SEATS)

This SI makes a change to the published Ground Handling Manual (GHM). The SI folder should have this instruction placed in it until its effective end date. GOM, GHP & other parties must ensure effective implementation of this SI at a local level. The accountable staff member at each airport must confirm to their easyJet Manager that the SI has been understood and embedded with all applicable Ground Crew. Local cascade may include some or all of the following:

- a signed read and brief, regular team briefing sessions to ensure Ground Crew understand SI content
- specific training and assurance of content comprehension by Ground Crew
- review of local audit checklists & training material to include any changes

STATION INSTRUCTION



A320 188Y SEATMAP

CABIN ZONE	ROW	A	B	C	D	E	F
	1	UF/R	UF/R	UF/R	UF/R	UF	UF
	2	UF	UF	UF	UF	UF	UF
	3	UF	UF	UF	UF	UF	UF
	4	UF	UF	UF	UF	UF	UF
OA 1-10 (Max 60)	5	UF	UF	UF	UF	UF	UF
	6	UF	UF	UF	UF	UF	UF
	7	X	X	X	X	X	X
	8	X	X	X	X	X	X
	9	X	X	X	X	X	X
	10	X	X	X	X	X	X
	11	X	X	X	X	X	X
	12	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	13	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	14	X	X	X	X	X	X
OB 11-20 (Max 60)	15	X	X	X	X	X	X
	16	X	X	X	X	X	X
	17	X	X	X	X	X	X
	18	X	X	X	X	X	X
	19	X	X	X	X	X	X
	20	X	X	X	X	X	X
	21	X	X	X	X	X	X
	22	X	X	X	X	X	X
	23	X	X	X	X	X	X
	24	X	X	X	X	X	X
OC 21-32 (Max 68)	25	X	X	X	X	X	X
	26	X	X	X	X	X	X
	27	X	X	X	X	X	X
	28	X	X	X	X	X	X
	29	X	X	X	X	X	X
	30	X	X	X	X	X	X
	31	X	X	X	R	X	X
	32		B	B			

Notes:

*R – RESTRICTED SEATING (CHIPPED) – REFER TO GHM 1.1.4.3

*X – STANDARD SEAT

*UF – UPFRONT SEATING

*EL – EXTRA LEGROOM SEATING

*B – Blocked Seat – No allocated seating

*ONLY 1 INFANT PER ROW OF 3 SEATS PERMITTED - E.G 1 INFANT IN ABC AND 1 INFANT IN DEF (INFANTS CANNOT OCCUPY RESTRICTED SEATS)

This SI makes a change to the published Ground Handling Manual (GHM). The SI folder should have this instruction placed in it until its effective end date. GOM, GHP & other parties must ensure effective implementation of this SI at a local level. The accountable staff member at each airport must confirm to their easyJet Manager that the SI has been understood and embedded with all applicable Ground Crew. Local cascade may include some or all of the following:

- a signed read and brief, regular team briefing sessions to ensure Ground Crew understand SI content
- specific training and assurance of content comprehension by Ground Crew
- review of local audit checklists & training material to include any changes

STATION INSTRUCTION



A319 156Y SEATMAP

CABIN ZONE	ROW	A	B	C	D	E	F
	1	UF/R	UF/R	UF/R	UF/R	UF	UF
	2	UF	UF	UF	UF	UF	UF
	3	UF	UF	UF	UF	UF	UF
OA 1-9 (Max 54)	4	UF	UF	UF	UF	UF	UF
	5	UF	UF	UF	UF	UF	UF
	6	X	X	X	X	X	X
	7	X	X	X	X	X	X
	8	X	X	X	X	X	X
	9	X	X	X	X	X	X
	10	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	11	EL/R	EL/R	EL/R	EL/R	EL/R	EL/R
	12	X	X	X	X	X	X
OB 10-18 (Max 54)	13	X	X	X	X	X	X
	14	X	X	X	X	X	X
	15	X	X	X	X	X	X
	16	X	X	X	X	X	X
	17	X	X	X	X	X	X
	18	X	X	X	X	X	X
	19	X	X	X	X	X	X
	20	X	X	X	X	X	X
	21	X	X	X	X	X	X
OC 19-26 (Max 48)	22	X	X	X	X	X	X
	23	X	X	X	X	X	X
	24	X	X	X	X	X	X
	25	X	X	X	X	X	X
	26	X	X	R	R	X	X

Notes:

*R – RESTRICTED SEATING (CHIPPED) – REFER TO GHM 1.1.4.3

*X – STANDARD SEAT

*UF – UPFRONT SEATING

*EL – EXTRA LEGROOM SEATING

*ONLY 1 INFANT PER ROW OF 3 SEATS PERMITTED - E.G 1 INFANT IN ABC AND 1 INFANT IN DEF (INFANTS CANNOT OCCUPY RESTRICTED SEATS)

This SI makes a change to the published Ground Handling Manual (GHM). The SI folder should have this instruction placed in it until its effective end date. GOM, GHP & other parties must ensure effective implementation of this SI at a local level. The accountable staff member at each airport must confirm to their easyJet Manager that the SI has been understood and embedded with all applicable Ground Crew. Local cascade may include some or all of the following:

- a signed read and brief, regular team briefing sessions to ensure Ground Crew understand SI content
- specific training and assurance of content comprehension by Ground Crew
- review of local audit checklists & training material to include any changes