

BULLETIN



Issue:	2023-02
From:	Corendon Airlines Ground Operations
Date	5/24/2023
Subject:	Headcount Procedure Change after Boarding is completed

Dear Partners,

We would like to share the procedure change for the head count after the boarding.

The head count process will not be performed by the cabin crew. Once the boarding is completed, the aircraft access door will be closed by the cabin crew.

Therefore Checking the Boarding cards during boarding and transit boarding has been more importance.

At this point we kindly ask you to pay maximum care and attention when checking the Boarding cards for the flight number and destination.

The GOM section 2.1.5 will be revised with the immediate time.

Please instruct the related handling agents accordingly.

Thank you for your cooperation

Ground Operation Department
Corendon Airlines