


GROUND SAFETY BULLETIN



Compartment separator nets and cargo door barrier net (HLM 9.1.4)



During handling, nets must **always** remain inside the compartment and must never hang outside, to prevent them from getting caught on equipment, being torn off, or picking up FOD that could damage the compartment.

This bulletin is published by the Safety Department and intended for the promotion of the Safety culture. Its content is complementary to and does not supersede nor modify current Operations Manual provisions. The content of this Safety Bulletin is confidential: reproduction and/or distribution requires specific written approval by ITA Airways. Any clarification or information request can be forwarded to: sicurezza.volo@ita-airways.com