




A220 CHOCKS & CONES (ref. HLM 5.7.4, HLM 5.7.5)



5.7.4 USE OF MARKER CONES



5.7.5 CHOCKING OF AIRCRAFT



This bulletin is published by the Safety Department and intended for the promotion of the Safety culture. Its content is complementary to and does not supersede nor modify current Operations Manual provisions. The content of this Safety Bulletin is confidential: reproduction and/or distribution requires specific written approval by ITA Airways. Any clarification or information request can be forwarded to: sicurezza.volo@ita-airways.com