

SAFETY BULLETIN (SB 2/2023)

airBaltic

Engine cooling before shut down

The minimum cooling period of engines after landing will be increased to 5 min, meaning that after aircraft has landed and engines have been set to idle, at least 5 minutes of engine cooling are required, before they can be shut down. This extra time will specifically be recognizable at airports, where taxi-in times are short, meaning aircraft might be standing on stand for a prolonged time with running engines.

Please inform all staff regarding this change and the required discipline not to enter the Equipment Restraint Area (ERA) while the engines are running and the anti-collision lights are on.



Read and Signed confirmation shall be sent to Ground_DOC@airbaltic.com