

FROM/TO FLIGHT

A/C REG VERSION

GATE TARMAC CREW

DATE

TIME

FRA NCE X38914F

DABKI FERRY

3/1

05Feb25

0341

PLANNED JOINING LOAD

NCE Y 0 C 0 M 0 B 0

EZFW 42964 KGS

JOINING SPECS

LOADING INSTRUCTION

CPT H1 MAX 741

:H1

:NO-FIT

:REPORT

CPT H2 MAX 2209

:H2

:NO-FIT

:REPORT

CPT H3 MAX 3437

:H3

:NO-FIT

:REPORT

CPT H4 MAX 570

:H4

:NO-FIT

:REPORT

COMPT.	H1	H2	H3	H4
TRANSIT KG.	0	0	0	0
RELOAD KG.	0	0	0	0
SUBTOTAL	0	0	0	0
ONLOAD KG.	0	0	0	0
TOTAL KG.	0	0	0	0
MAXIMUM KG.	741	2209	3437	570

EMPTY HOLDS CHECK COMPLETED PRIOR TO ANY BAGGAGE ONLOAD.

HOLD NETS SECURE,CLIPS CLOSED,LOCKS UP AND LOAD SECURED BEFORE DEPARTURE

NAME OF LOADING AGENT:

SIGNATURE:

THIS AIRCRAFT HAS BEEN LOADED IN ACCORDANCE WITH THESE INSTRUCTIONS AND THE DEVIATIONS SHOWN ON THIS REPORT. THE ULD'S AND BULK LOAD HAVE BEEN SECURED IN ACCORDANCE WITH TUI INSTRUCTIONS

NAME OF RESPONSIBLE

LOADING SUPERVISOR:

SIGNATURE: