



Delay TUI

Hello all,

From now on we have to give DLC from 1min for all TUI flights.
There is no 5min tolerance anymore.



Ground Handling Manual Part 1 Station Operations - Communication

12.1.4.1 Delay Reason Codes for TUIfly

Delay codes are based on the following standard turn around times:

TUIfly defined a standard turnaround time of 50 minutes for X3 flights.

For triangle flights the turnaround time on first station is 45 minutes and on second station 50 minutes.

An exceedance of this ground time of more than 1 minute counts as delay, which shall be explained in the respective MVT-message.

For DPAG flights a ground time of 120 minutes is determined.

Even if your scheduled turn around time exceeds those times, delay shall be noted referring to given standard times.

Delay codes can also be found in the TAGO Portal, Documents, TUIfly Germany, Manuals, Appendix I10 Delay Codes.

Thank you!

Laura