

DHS NEWSPAPER



WEEKLY 30

STATION: FRA OPS

Engine Start during P/B:

From now on, engines are only allowed to start once the A/C is pushed in a straight line to prevent broken towbars.



AZ A/C used for EJU flights:

Please always check the MEL report of AZ and EasyJet in case AZ is operating the flight.

New Techs for TUI:

Starting from April 27th Bosten Air will be the new Tech company for TUI.

In case of any issues, please report.

Flight Files:

You must complete all your flight files asap.

In case you are missing a page, please inform Backoffice and let them finish your file later. The flight files must be completed and cannot be just thrown away.

FOD Check:

We recently had a FOD incident where an A/C arrived with a damage tire.

Please make sure that your FOD check is done across the whole position prior to arrival.



Inbound LDMs/PSM:

Inbound LDMs/PSMs must be read before arrival and the load master informed about any specials.

One WCLB was left on board overnight.

SEE SOMETHING, SAY SOMETHING!

Staff Member Report - FRA



Powered by

SafetyCulture