

<b>Loading Info</b>	
Local Baggage	pcs
TRS Baggage	pcs
BUGGY , DAA, WCH, GATE Baggage	pcs
RUSG Baggage	pcs
TOTAL Pcs. Loading	pcs

Station	Flight No	A/C Reg	STD	From	Via	To/Dest	Date
MUC	1022	TC-NCY	10:27	-	-	SAW	17/02/2026

<b>Special Load Instructions / Özel Yük Talimatları</b>
(AVI, WEA, HEA, HUM, DAA, etc) / (Kedi / Kopek / Agir Yuk, Cenaze, Teknik Malzeme, vs. )
H1 100BY+BT H3 REST BY+BT NOTOC NO

<b>Note:</b>
Note: Weapon and Crewbagge must be loaded only forward Hold/ Not: Silah ve Ekip Bagaji on ambara yuklenmelidir.

<b>Load Planner(Operation Agent)/ Operasyon Memuru</b>	
This form filled in accordance with AHM, DGR and company regulations. / Bu form AHM DGR ve sirket duzenlemelerine uygun olarak duzenlenmistir.	
Name Surname / Ad Soyad	Signature / Imza

<b>Load Planner(Operation Agent)/ Operasyon Memuru</b>	
This aircraft has been loaded in accordance with these instructions including the deviations recorded and cargo holds height limitations (6cm). The load has been secured in accordance with company regulations / Bu ucak, yukleme formatinda yer aldigi sekilde ve ambar yukseklik limitlerine (6cm) uygun olarak yuklenmistir. Havayolu kurallarina gore yukler emniyet altina alinmistir.	
Name Surname / Ad Soyad	Signature / Imza

	AFT HOLD / ARKA AMBAR			FWD HOLD / ON AMBAR
AT ARRIVAL GELEN YUK	5 MUC AFT DOOR	4 MUC AFT DOOR	3 MUC	1 MUC FWD DOOR
LOADING INSTRUCTION YUKLEME TALIMATI	5 SAW NIL AFT DOOR	4 SAW NIL AFT DOOR	3 SAW REST BY AFT DOOR	1 SAW 100 BY FWD DOOR
ACTUAL LOADING GERCEKLESEN YUKLEME	5 SAW AFT DOOR	4 SAW AFT DOOR	3 SAW	1 SAW FWD DOOR

<b>Remarks / Aciklamalar</b>
------------------------------

**Please Fill In The Checklist (RAMP)/ Lutfen Kontrol Listesini Doldurunuz (RAMP)**

Any defects of cargo holds, nets, and locks must be reported to the captain and PGT Ground Ops Department. Relevant LIR, LS, and GSR forms must be sent to PGT Ground Ops Department. /	<input type="checkbox"/> Check	Cargo holds have been checked for any unsecured items after offloading completed, and cargo hold nets and locks have been checked, fitted, and secured after loading completed. /	<input type="checkbox"/> Check
Kargo ambarlari, aglari ve kilitlelerine iliskin herhangi bir hasar, mesul kaptana ve PGT Yer Isletme Departmani'na rapor edilmelidir. Ilgili LIR, LS ve GSR formu PGT Yer Isletme Departmani'na gonderilmelidir.	<input type="checkbox"/> N/A	Ambar bosaltildiktan sonra guvenlik riski yaratabilecek unsurlar icin kontrol edilmiş ve yukleme tamamlandıktan sonra ambar aglari ve kilitleleri kontrol edilmiş ve guvenli bir sekilde baglanmiş/kilitlenmiştir.	<input type="checkbox"/> N/A