

Loading Info	
Local Baggage	pcs
TRS Baggage	pcs
BUGGY , DAA, WCH, GATE Baggage	pcs
RUSG Baggage	pcs
TOTAL Pcs. Loading	pcs

Station	Flight No	A/C Reg	STD (Local Time)	From	Via	To/Dest	Date
MUC	1022	TC-RBF	16:35	-	-	SAW	09/04/2026

AFT HOLD / ARKA AMBAR

FWD HOLD / ON AMBAR

Special Load Instructions / Özel Yük Talimatları
(AVI, WEA, HEA, HUM, DAA, etc) / (Kedi / Kopek / Agir Yuk, Cenaze, Teknik Malzeme, vs.)
H2 ALL BY+BT NOTOC NO

Note:
Note: AVIH FWD Hold, Weapon Hold 1, Crewbaggage must be loaded Hold 5.
Not: AVIH on ambara, Silah Hold 1'e, Ekip bagaji Hold 5'e yuklenmelidir.

Load Planner(Operation Agent) / Operasyon Memuru	
This form filled in accordance with AHM, DGR and company regulations. / Bu form AHM DGR ve sirket duzenlemelerine uygun olarak duzenlenmistir.	
Name Surname / Ad Soyad	Signature / Imza

Loading Team Leader / Yükleme Sorumlusu	
This aircraft has been loaded in accordance with these instructions including the deviations recorded and cargo holds height limitations (6cm). The load has been secured in accordance with company regulations / Bu uçak, yukleme formatında yer aldığı şekilde ve ambar yükseklik limitlerine (6cm) uygun olarak yuklenmiştir. Havayolu kurallarına göre yukler emniyet altına alınmıştır.	
Name Surname / Ad Soyad	Signature / Imza

AT ARRIVAL GELEN YUK	5 MUC	4 MUC	3 MUC	2 MUC	1 MUC
LOADING INSTRUCTION YUKLEME TALIMATI	5 SAW NIL	4 SAW NIL	3 SAW NIL	2 SAW ALL BY ALL BT	1 SAW NIL
ACTUAL LOADING GERCEKLESEN YUKLEME	5 SAW	4 SAW	3 SAW	2 SAW	1 SAW

Remarks / Aciklamalar

Please Fill In The Checklist (RAMP)/ Lütfen Kontrol Listesini Doldurunuz (RAMP)

Any defects of cargo holds, nets, and locks must be reported to the captain and PGT Ground Ops Department. Relevant LIR, LS, and GSR forms must be sent to PGT Ground Ops Department. /	<input type="checkbox"/> Check	Cargo holds have been checked for any unsecured items after offloading completed, and cargo hold nets and locks have been checked, fitted, and secured after loading completed. /	<input type="checkbox"/> Check
Kargo ambarları, aqları ve kilitlerine ilişkin herhangi bir hasar, mesul kaptana ve PGT Yer İşletme Departmanı'na rapor edilmelidir. İlgili LIR, LS ve GSR formu PGT Yer İşletme Departmanı'na gönderilmelidir.	<input type="checkbox"/> N/A	Ambar bosaltıldıktan sonra güvenlik riski yaratabilecek unsurlar için kontrol edilmiş ve yukleme tamamlandıktan sonra ambar aqları ve kilitleri kontrol edilmiş ve güvenli bir şekilde bağlanmış/kilitlenmiştir.	<input type="checkbox"/> N/A