

PEGASUS AIRLINES LOADING INSTRUCTION REPORT-LIR

PREPARED BY-OPS :

APPROVED BY-OPS :

A/L	FLT	TYPE	STATUS	FROM	TO	REG	VER	DTE	TIME	EDNO
PC	5036	J	RZ	FRA	AYT	TC-NCU	Y186	15/06/2024	03:30	0 / 2

CPT 1 MAX :3402

ONLOAD AYT B/1350/90

SPECS AYT

REPORT

CPT 1 TOTAL :.....

CPT 3 MAX :2426

ONLOAD AYT B/750/50

SPECS AYT

REPORT

CPT 3 TOTAL :.....

CPT 4 MAX :2110

ONLOAD AYT B/150/10

SPECS AYT

REPORT

CPT 4 TOTAL :.....

CPT 5 MAX :500

ONLOAD AYT NIL

SPECS AYT

REPORT

CPT 5 TOTAL :.....

REPORT

SPECIAL LOADS

H1-90xBY H3-REST BY H4-ALL BT

LÜTFEN KONTROL LİSTESİNİ DOLDURUNUZ (RAMP)

Kargo ambarları, ağırları ve kilitlerine | X | N/A
ilişkin herhangi bir hasar, mesul kaptana ve
PGT Yer İşletme Departmanı'na rapor
edilmelidir. İlgili LIR, LS ve GISR formu PGT
Yer İşletme Departmanına gönderilir.

Ambar boşaldıktan sonra güvenlik riski | X | N/A
yaratailecek unsurlar için kontrol edilmiş ve
yükleme tamamlandıktan sonra ambar ağırları ve
kilitleri kontrol edilmiştir.

LOADING TEAM LEADER

Bu uçak yükleme formunda yazıldığı şekilde ve ambar yükseklik
limitlerine(6 cm) uygun olarak yüklenmiştir. Havayolu kurallarına göre
yükler emniyet altına alınmıştır.

Ad Soyad:

İmza: