

PEGASUS AIRLINES LOADING INSTRUCTION REPORT-LIR

PREPARED BY-OPS :

APPROVED BY-OPS :

A/L	FLT	TYPE	STATUS	FROM	TO	REG	VER	DTE	TIME	EDNO
PC	994	J	RZ	FRA	SAW	TC-RDG	Y239	09/06/2024	06:40	0 / 1

CPT 1 MAX :2202

ONLOAD SAW B/900/60

SPECS SAW

REPORT

CPT 1 TOTAL :.....

CPT 2 MAX :3468

ONLOAD SAW B/300/20 C/394/6

SPECS SAW

REPORT

CPT 2 TOTAL :.....

CPT 3 MAX :3587

ONLOAD SAW B/1050/70

SPECS SAW

REPORT

CPT 3 TOTAL :.....

CPT 4 MAX :2083

ONLOAD SAW B/450/30

SPECS SAW

REPORT

CPT 4 TOTAL :.....

CPT 5 MAX :800

ONLOAD SAW NIL

SPECS SAW

REPORT

CPT 5 TOTAL :.....

REPORT

SPECIAL LOADS

H1-60BY H2-ALL CARGO/20BY H3-REST BY H4-ALL BT

LÜTFEN KONTROL LİSTESİNİ DOLDURUNUZ (RAMP)

Kargo ambarları, ağları ve kilitlerine | X | N/A
ilişkin herhangi bir hasar, mesul kaptana ve
PGT Yer İşletme Departmanı'na rapor
edilmelidir. İlgili LIR, LS ve GISR formu PGT
Yer İşletme Departmanına gönderilir.

Ambar boşaldıktan sonra güvenlik riski | X | N/A
yaratılacak unsurlar için kontrol edilmiş ve
yükleme tamamlandıktan sonra ambar ağları ve
kilitleri kontrol edilmiştir.

LOADING TEAM LEADER

Bu uçak yükleme formunda yazıldığı şekilde ve ambar yükseklik
limitlerine(6 cm) uygun olarak yüklenmiştir. Havayolu kurallarına göre
yükler emniyet altına alınmıştır.

Ad Soyad:

İmza: