

PEGASUS AIRLINES LOADING INSTRUCTION REPORT-LIR

PREPARED BY-OPS :

APPROVED BY-OPS :

A/L	FLT	TYPE	STATUS	FROM	TO	REG	VER	DTE	TIME	EDNO
PC	996	J	RZ	FRA	SAW	TC-RDZ	Y239	16/08/2024	10:36	0 / 1

CPT 1 MAX :2202

ONLOAD SAW B/750/50

SPECS SAW

REPORT

CPT 1 TOTAL :.....

CPT 2 MAX :3468

ONLOAD SAW C/568/37

SPECS SAW

REPORT

CPT 2 TOTAL :.....

CPT 3 MAX :3587

ONLOAD SAW B/1650/110

SPECS SAW

REPORT

CPT 3 TOTAL :.....

CPT 4 MAX :2083

ONLOAD SAW B/750/50

SPECS SAW

REPORT

CPT 4 TOTAL :.....

CPT 5 MAX :800

ONLOAD SAW NIL

SPECS SAW

REPORT

CPT 5 TOTAL :.....

REPORT

SPECIAL LOADS

H1-50BY H2-ALL CARGO H3-REST BY+BT UNTIL 110TTL H4-REST BT

LÜTFEN KONTROL LİSTESİNİ DOLDURUNUZ (RAMP)

Kargo ambarları, ağırları ve kilitlerine | X | N/A
ilişkin herhangi bir hasar, mesul kaptana ve
PGT Yer İşletme Departmanı'na rapor
edilmelidir. İlgili LIR, LS ve GISR formu PGT
Yer İşletme Departmanına gönderilir.

Ambar boşaldıktan sonra güvenlik riski | X | N/A
yaratılacak unsurlar için kontrol edilmiş ve
yükleme tamamlandıktan sonra ambar ağırları ve
kilitleri kontrol edilmiştir.

LOADING TEAM LEADER

Bu uçak yükleme formunda yazıldığı şekilde ve ambar yükseklik
limitlerine(6 cm) uygun olarak yüklenmiştir. Havayolu kurallarına göre
yükler emniyet altına alınmıştır.

Ad Soyad:

İmza: