

Hermes 17:49 07/29/24

CARGO MANIFEST Type 4

Owner or Operator: Air Baltic Corporation

Marks of Nationality/Registration Number:

Flight No: BT 252 Date: 30Jul24

Point of loading: Hamburg, Hamburg Fuhlsbuettel, Germany

Point of unloading: Riga, Riga Intl., Latvia

Pallet/ULD No: LOCO/Transit:							
No	Air Waybill and Part No	No Of Pieces	Nature of goods	Gross Weight	ORI/DES	Remarks	Official use only

ULD: BULK RIX

COMMERCIAL CARGO

LOCAL CARGO

1	657-14085772	1	CIVIL AC PARTS	4,9	HAM/RIX	RFL	C
2	657-14085783	1	CIVIL AC PARTS	6,2	HAM/RIX	RFL,RCM	C
Total		2		11,1			

BT - Air Baltic Corporation

ULD/Bulk Load Weight Statement

ALL WEIGHTS IN KILOGRAM

Station HAM	Flight No. 252	Registration	Date 30/Jul/2024
----------------	-------------------	--------------	---------------------

Unit Load Devices (ULD)

T	ULD ID Code	Gross Weight	Net Weight	Unloading Point	Dest	Remarks	Sign
---	-------------	--------------	------------	-----------------	------	---------	------

1	TROLLEY		12 KG		RIX	R F L R C M	TB
---	---------	--	-------	--	-----	-------------	----

Total Bulk Weights: 12,0

SPECIAL LOAD – NOTIFICATION TO CAPTAIN											
Station of Loading HAM		Flight Number BT252		Date 30Jul24		Aircraft Registration		Reported By Mr. Thomas Boettiger			
								LUG aircargo handling GmbH Niederlassung Hamburg HACC Geb. 391, Weg beim Jäger 200 22335 Hamburg			
DANGEROUS GOODS											
Station of unloading	Airwaybill number	Proper shipping name		Class or Division for class 1 Compat.grp	UN or ID number	Sub Risk	Number Of Packages	Net quantity Or TI	Radio Active Category	Packing Group	Code
1 RIX	65714085783	AMINES, LIQUID, CORROSIVE, N.O.S. (.)		8	UN2735			0,54 L		III	RCM
2 RIX	65714085783	PAINT RELATED MATERIAL		3	UN1263			3,79 L		III	RFL
3 RIX	65714085772	FLAMMABLE LIQUID, N.O.S. (.)		3	UN1993		1	0,15 L		II	RFL
Lines 1 to 2 "All Packed In One"											
3H BULK											
OTHER SPECIAL LOAD											
Stat of unload	Airway bill Number	Content and Description		Number Of packages	Quantity	Supplementary Information		Code	Loaded		
									ULD ID		
									Position		
There is no evidence that any damaged or leaking packages containing dangerous goods have been loaded on the aircraft											
Loading Supervisor's Signature		Captain's Signature		Other Information:							