

| COMPARTMENT 5 | | COMPARTMENT 4 | | COMPARTMENT 3 | | COMPARTMENT 1 | | | |
|----------------------|---|---|-------------------------------|---|---|-----------------------------------|----|-------------------------------|--------------------------------|
| LOADING INSTRUCTIONS | 5 | 42 | 41 | 32 | 31 | 13 | 12 | 11 | |
| | CREW FCO BRr 0pcs FCO BJr 2pcs FCO BGr 0pcs | | AKH AZ FCO BT 30pcs | AKH AZ FCO BT 25pcs AZ1767 /CTA | AKH AZ 17438 FCO C 159kg | AKH AZ 17272 FCO C 159kg | N | AKH AZ FCO BYr 8pcs | AKH AZ FCO BTr 20pcs |
| DEP REPORT | 5 | 42 | 41 | 32 | 31 | 13 | 12 | 11 | |
| | DOOR | | DOOR | | | | | DOOR | |
| LOCKING INSTRUCTIONS | | (Ret) Fixed End Stop Pallet Lock Raised Pallet Lock Lowered Lateral Guide Raised Lateral Guide Lowered Container Stop Raised Container Stop Lowered | | | | | | | |
| L | 42 | | 41 | 32 | 31 | 12 | | | 11 |
| R | 42 | | 41 | 32 | 31 | 12 | | | 11 |
| SPECIAL INSTRUCTIONS | | SPECIAL LOAD DETAILS | | | CARGO COMPARTMENT VISUAL CHECK PERFORMED / SIGNATURE _____ THIS AIRCRAFT HAS BEEN LOADED IN ACCORDANCE WITH THESE INSTRUCTIONS INCLUDING THE DEVIATIONS SHOWN ON THE REPORT, THE CONTAINERS, PALLETS AND BULK LOAD HAVE BEEN SECURED IN ACCORDANCE WITH COMPANY REGULATIONS. SIGNATURE / NAME _____ CAPTAIN SIGNATURE FOR ACCEPTANCE_____ SIGNED PRINT NAME | | | | |