








AZ 403	EIHXA	05Jul25	EX FRA	EDNO 1	PREPARED BY markoski alexsandar		PHONE +4915123211415	DECK LOWER	FWD ➡	PAGE 1 OF 1
					TIME 11:40	TIME SENT 08:37	A321-200N			

COMPARTMENT 5			COMPARTMENT 4			COMPARTMENT 3			COMPARTMENT 2			COMPARTMENT 1		
LOADING INSTRUCTIONS	53	52	51	42	41	33	32	31	23	22	21	12	11	
	CREW FCO BRr 0pcs FCO BGr 0pcs FCO BTr 0pcs FCO BJr 8pcs			AKH AZ FCO BY 34pcs	AKH AZ FCO BT 17pcs	AKH AZ FCO BYr 0pcs	AKH AZ FCO BT 0pcs	PKC AZ 25781 FCO C 325kg	AKH AZ FCOBT 15pcs	AKH AZ FCOBT 22pcs AZ848 /JED	AKH AZ FCOBT 21pcs AZ852 /ACC	AKH AZ FCOBT 21pcs AZ852 /ACC	AKH AZ FCOBT 21pcs AZ852 /ACC	
	DOOR			DOOR									DOOR	
DEP REPORT	53	52	51	42	41	33	32	31	23	22	21	12	11	
	DOOR			DOOR									DOOR	

LOCKING INSTRUCTIONS		 (Ret) Fixed End Stop	 Pallet Lock Raised	 Pallet Lock Lowered	 Lateral Guide Raised	 Lateral Guide Lowered	 Container Stop Raised	 Container Stop Lowered			
L		42	41	33	32	31	23	22	21	12	11
R		42	41	33	32	31	23	22	21	12	11

SPECIAL INSTRUCTIONS 11: ACC 12: ACC 21: ACC 22: JED 23: BT 31: C 32: BT 33: BY 41:SHORT BT 42: BY REST: CREW AND BG		SPECIAL LOAD DETAILS		CARGO COMPARTMENT VISUAL CHECK PERFORMED / SIGNATURE _____ THIS AIRCRAFT HAS BEEN LOADED IN ACCORDANCE WITH THESE INSTRUCTIONS INCLUDING THE DEVIATIONS SHOWN ON THE REPORT, THE CONTAINERS, PALLETS AND BULK LOAD HAVE BEEN SECURED IN ACCORDANCE WITH COMPANY REGULATIONS. SIGNATURE / NAME _____ CAPTAIN SIGNATURE FOR ACCEPTANCE_____ SIGNED PRINT NAME	
---	--	----------------------	--	---	--