

PEGASUS AIRLINES LOADING INSTRUCTION REPORT-LIR

PREPARED BY-OPS : BURAK

APPROVED BY-OPS :

A/L	FLT	TYPE	STATUS	FROM	TO	REG	VER	DTE	TIME	EDNO
PC	5036	J	CI	FRA	AYT	TC-NCI	Y186	19/05/2023	04:09	0 / 1

CPT 1 MAX :3402

ONLOAD AYT B/1500/100

SPECS AYT

REPORT

CPT 1 TOTAL :.....

CPT 3 MAX :2426

ONLOAD AYT B/900/60

SPECS AYT

REPORT

CPT 3 TOTAL :.....

CPT 4 MAX :2110

ONLOAD AYT B/300/20

SPECS AYT

REPORT

CPT 4 TOTAL :.....

CPT 5 MAX :500

ONLOAD AYT NIL

SPECS AYT

REPORT

CPT 5 TOTAL :.....

REPORT

SPECIAL LOADS

LIR H1-100x H3-60x H4-rest

LÜTFEN KONTROL LİSTESİNİ DOLDURUNUZ (RAMP)

Kargo ambarları, ağırları ve kilitlerine | X | N/A
ilişkin herhangi bir hasar, mesul kaptana ve
PGT Yer İşletme Departmanı'na rapor
edilmelidir. İlgili LIR, LS ve GISR formu PGT
Yer İşletme Departmanına gönderilir.

Ambar boşaldıktan sonra güvenlik riski | X | N/A
yaratailecek unsurlar için kontrol edilmiş ve
yükleme tamamlandıktan sonra ambar ağırları ve
kilitleri kontrol edilmiştir.

LOADING TEAM LEADER

Bu uçak yükleme formunda yazıldığı şekilde ve ambar yükseklik
limitlerine(6 cm) uygun olarak yüklenmiştir. Havayolu kurallarına göre
yükler emniyet altına alınmıştır.

Ad Soyad:

İmza: