

## PEGASUS AIRLINES LOADING INSTRUCTION REPORT-LIR

PREPARED BY-OPS : BURAK

APPROVED BY-OPS :

| A/L | FLT  | TYPE | STATUS | FROM | TO  | REG    | VER  | DTE        | TIME  | EDNO  |
|-----|------|------|--------|------|-----|--------|------|------------|-------|-------|
| PC  | 5036 | J    | RZ     | FRA  | AYT | TC-NCU | Y186 | 02/06/2023 | 05:43 | 0 / 1 |

CPT 1 MAX :3402

ONLOAD AYT B/1500/100

SPECS AYT

REPORT

CPT 1 TOTAL :.....

CPT 3 MAX :2426

ONLOAD AYT B/900/60

SPECS AYT

REPORT

CPT 3 TOTAL :.....

CPT 4 MAX :2110

ONLOAD AYT B/600/40

SPECS AYT

REPORT

CPT 4 TOTAL :.....

CPT 5 MAX :500

ONLOAD AYT NIL

SPECS AYT

REPORT

CPT 5 TOTAL :.....

REPORT

SPECIAL LOADS

LIR H1-100X H3-60X H4-REST

## LÜTFEN KONTROL LİSTESİNİ DOLDURUNUZ (RAMP)

Kargo ambarları, ağırları ve kilitlerine | X | N/A  
ilişkin herhangi bir hasar, mesul kaptana ve  
PGT Yer İşletme Departmanı'na rapor  
edilmelidir. İlgili LIR, LS ve GISR formu PGT  
Yer İşletme Departmanına gönderilir.

Ambar boşaldıktan sonra güvenlik riski | X | N/A  
yaratailecek unsurlar için kontrol edilmiş ve  
yükleme tamamlandıktan sonra ambar ağırları ve  
kilitleri kontrol edilmiştir.

## LOADING TEAM LEADER

Bu uçak yükleme formunda yazıldığı şekilde ve ambar yükseklik  
limitlerine(6 cm) uygun olarak yüklenmiştir. Havayolu kurallarına göre  
yükler emniyet altına alınmıştır.

Ad Soyad:

İmza: